

## WEST Search History





DATE: Wednesday, November 16, 2005

Hide?	<u>Set</u> <u>Name</u>	<u>Query</u>	<u>Hit</u> <u>Count</u>
		<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L36	l8 and 148/608.ccls.	7
		<i>DB=USPT; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L35	6316117	2
<input type="checkbox"/>	L34	6316177 or 6488786 or 6723181	6
		<i>DB=JPAB; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L33	6316177 or 6488786 or 6723181	0
<input type="checkbox"/>	L32	l1 same (machin\$3 or machinability)	45
		<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L31	l29 and stainless and (precipitation or precipitate or particle)	69
<input type="checkbox"/>	L30	l29 and stainless	69
<input type="checkbox"/>	L29	L28 and ((cu or copper) near (precipitation or precipate or particle))	124
<input type="checkbox"/>	L28	l20 and (age or aging or aged)	7076
<input type="checkbox"/>	L27	L26 and ((cu or copper) near (particle or precipitate or precipitation or enrich\$3))	107
<input type="checkbox"/>	L26	l20 and ( indium)	6117
<input type="checkbox"/>	L25	l20 and (in or indium)	46433
<input type="checkbox"/>	L24	L22 and ((cu or copper) near(precipitate or particle ))	4
<input type="checkbox"/>	L23	L22 and ((cu or copper)near(precipitate or particle ))	4
<input type="checkbox"/>	L22	L21 and stainless and (ferrit\$2 or martensit\$2)	262
<input type="checkbox"/>	L21	L20 and ((cu or copper) near (sn or tin))	3164
<input type="checkbox"/>	L20	steel and (c or carbon) and (cr or chromium) and (cu or copper) and (sn or tin or in or indium)	50792
<input type="checkbox"/>	L19	l8 and 148/607.ccls.	12
<input type="checkbox"/>	L18	L16 and 420/\$.ccls.	8
<input type="checkbox"/>	L17	L16 and 148/\$.ccls.	13
<input type="checkbox"/>	L16	L15 and (ferrit\$2 or martensit\$2)	544
<input type="checkbox"/>	L15	L14 and stainless	4913
<input type="checkbox"/>	L14	l8 and indium	6117
<input type="checkbox"/>	L13	L12 same ((cu or copper) near (particle or precipitate or age or aging or aged or enrich\$3))	3
<input type="checkbox"/>	L12	steel same stainless same (ferrit\$2 or martensit\$2) same (cu or copper) same (sn or tin or indium)	178

<input type="checkbox"/>	L11	L8 and 148/325.ccls.	70
<input type="checkbox"/>	L10	L8 and 420/60.ccls.	13
<input type="checkbox"/>	L9	L8 and 148/326.ccls.	24
<input type="checkbox"/>	L8	steel and (c or carbon) and (cr or chromium) and (cu or copper) and (sn or tin or indium)	25151
<i>DB=JPAB; PLUR=YES; OP=OR</i>			
<input type="checkbox"/>	L7	l1 and ((cu or copper) near (particle or precipitation or enrich\$3))	7
<input type="checkbox"/>	L6	L5 same stainless same (ferrit\$2 or martensit\$2)	6
<input type="checkbox"/>	L5	steel same(c or carbon) same (cr or chromium) same (cu or copper) same (sn or tin or indium)	228
<input type="checkbox"/>	L4	L2 same martensit\$2	34
<input type="checkbox"/>	L3	L2 same ferrit\$2	55
<input type="checkbox"/>	L2	L1 same stainless	216
<input type="checkbox"/>	L1	steel same(c or carbon) same (cr or chromium) same (cu or copper) same (sn or tin or in or indium)	902

END OF SEARCH HISTORY